

| Pre-treatment Tape Tack Measurement



JIS Z 0237–No.4

1.Pretreatment for testing sample .

Setting time is over 24Hr
under condition as below.

Temp:23±2..

Humidity:50±5%.


2.Collecting test–piece within Roll.

Cutting off which 3 turns from outside,
then collecting test–pieces.

Measurement


Adhesive Strength
(JIS Z0237 No.10)

180° peel method




Measurement

Probe Tack




Measurement

Probe Tack



Measurement

Probe Tack



Measurement

Holding Power Test Method

